

Report No. B52392

## RESEARCH TEST &amp; MEASUREMENT LAB WORK REQUEST

<input type="checkbox"/> Developmental <input checked="" type="checkbox"/> Design Acceptance <input type="checkbox"/> Pre-Pilot <input type="checkbox"/> Pilot <input type="checkbox"/> Production Acceptance		<u>AREA OF TESTING</u> <input type="checkbox"/> Safety Related <input type="checkbox"/> Litigation <input type="checkbox"/> Competitive Evaluation <input type="checkbox"/> Warehouse Audit <input checked="" type="checkbox"/> New Design <input type="checkbox"/> Cost Reduction <input type="checkbox"/> Design Change <input type="checkbox"/> State <u>ALOT</u> <input type="checkbox"/> Plant Assistance <input type="checkbox"/> Other	
<u>FIREARM STAT'S</u> MODEL: <u>700/NBAR</u> CAL. or GAGE: <u>30-06</u> BARREL TYPE: _____ PROOFED: YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		<u>REPORT REQ'D.</u> FORMAL _____ TEST RESULTS ONLY <input checked="" type="checkbox"/>	DATE REQUESTED: <u>8-27-85</u> DATE NEEDED BY: <u>9-4-85</u> REQUESTED BY: <u>F.H. Smith</u> WORK ORDER NO: <u>C-5005-314</u>
<u>TEST TYPE</u> <input type="checkbox"/> Strength Test <input type="checkbox"/> Ammunition Test <input type="checkbox"/> Dry Cycle Test <input type="checkbox"/> Photo/Video <input checked="" type="checkbox"/> Function Test <input type="checkbox"/> Environmental Test <input checked="" type="checkbox"/> Measurements <input type="checkbox"/> Other _____ <input type="checkbox"/> Accuracy Test <input type="checkbox"/> Customer Complaint <input type="checkbox"/> Endurance Test			

EXPLAIN IN DETAIL THE REASON FOR THIS TEST:

PLEASE MEASURE LOCK-TIME FOR NBAR  
BOLT ASSEMBLY

-GUNS REQUIRED: 700/NBAR SUPPLIED BY ENGINEERING

NOTE: NO firearms or parts will be tested in the Labs unless they are accompanied by a Work Request, and both are delivered to the Labs by the designer or engineer. All Work Requests are to be filled out in detail. No Exceptions.

DATE COMPLETED: 9/3/85  
 TEST COMPLETED BY: P. Grant  
 REPORT DATE: \_\_\_\_\_