

PRESS RELEASE

Contact: Carol Montague  
302-774-1266 or  
Sondra Fowler  
302-773-4191

REMINGTON RECALLS LIMITED NUMBER  
OF MODEL XP-100 HANDGUNS

The Remington Arms Company has announced the recall of a limited number of Model XP-100 pistols. The recall applies only to Model XP-100's purchased after January 1, 1987.

During routine servicing of Model XP-100's, Remington discovered that an incomplete factory operation involving the front trigger housing screw may have occurred in a limited number of guns. Although unlikely, during normal usage of affected guns, the front trigger housing screw may position itself in a manner that could promote unintentional firing upon release of the safety or upon closing of the bolt.

While this condition may not exist in all Model XP-100 pistols produced after the above date, Remington wishes to examine all such guns in the interest of customer safety and firearms quality. Any necessary adjustments will be made at no charge.

All owners of XP-100 pistols purchased after January 1, 1987 are requested to contact Remington by calling the toll free number

In U.S.A. - 800-634-2459  
In Canada - 800-634-5401

Callers will be assisted in determining if their gun is potentially affected and provided with directions on how to return it if necessary. Until such a determination is made, Remington requests the owners who have purchased these pistols since Jan. 1, 1987, not to load them.

No Remington firearms other than Model XP-100 pistols are affected by this potential condition and no other Remington models are involved in the recall.