

700 Custom. Springfield

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 026289
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-15-72
 FIRED AMMO TYPE: _____ FROM: GALLINGHAM & JONES INC. CHENALIS, WASH.
 & CONDITION: _____ GUN #: 6295844
 PROOF: R.E.P.-E INSP. 9 TEST: 18 CODE: X5 = 12/69
 HEADING: _____ GA./CAL.: 300 WIN. MAG.
 BREECH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. .020)
CONNECTOR 1.085 (MODEL DRAWING 1.080) SAFETY 2.91 (MODEL
DRAWING 2.92) TRIGGER BINDING IN HOUSING.

COMPLAINT: FIRED WHEN CLOSING ACTION.INCIDENT: FOLLOW DOWN.

COMMENTS: THE BINDING TRIGGER PROBABLY FAILED TO
RETRACT CAUSING THE ACTION TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3194

AL 0029724