

(Model 7400 cont.)

Reassembly

Fore end screw

Affects accuracy

Do not use swivel studs that screws in place of FE screw,
use barrel band

Possible malfunctions

Jamming – what causes this?

Ammunition

“hot” or high energy, light magnum loads

Military surplus

Dirty gun – chamber pitted from misuse

Shouldering

Care and cleaning

Model 7600

Brief history including 760

Cycle of operation

Similarities to 7400

Disassembly

Stock and fore end

Receiver assembly

20-gauge shotgun receiver

Action bar assembly

Detachable magazine

Trigger assembly

Common fire control

Barrel assembly

Locking lugs in barrel

Barrel to receiver fit

Reassembly

Possible malfunctions

Most reliable firearm we make

Very few repairs

Opens on firing – this is normal

Care and cleaning

No hot loads

Chamber