## Internet FAQ's

## Parts & Repair:

## How can I get another ISS key to unlock my firearm?

In order to send out the key, you will need to send or fax wither a copy of your receipt or a copy of your driver's license to the address below and we'll be glad to provide you with a key.

Remington Arms Company P.O. Box 700 870 Remington Drive Madison, NC 27025-0700 336-548-7801-fax

If you wish to purchase additional keys, you can order these by calling us at 1-800-243-9700 M-F 9-5 EST.

Do you do updates on the Model 3200? Remington does offer an update on the Model 3200. This service is offered to replace parts that can be worn over time and to help insure an extended life for the firearm. The cost for this update is \$350 through our factory repair department. Generally this type of work will take approximately 10-12 weeks to complete. You can find instructions for sending your firearm to our factory in the Support>Repair section of our website.

The following parts involved in the update are

Bottom Tang

Bottom Tang Pin

Bottom Tang Screw

Ejector Stop Pin

Ejector Tip

Ejector Tip Rods (left & right)

Firing Pin Retractor

Hammer Assy (left & right)

Hammer Cocking Rod

Sear Block

Sear Block Pin

Sear (left & right

Sear Spring

Selector Block

Strut

Tang Block Screw

Tang Block Slot Nut

Tang Connecting Block

Tang Struck

Tang Strug Pm

Top Lock

Top Lock Latch

Top Lock Lever Plunger Assy

Top Lock Lever Serew

Trigger Adjusting Screw

Trigger Adjusting Screw Nut

