100	D NUMBER NOT TO CAOTON (ONE OFFICE ATTONIO	E E
	NIPPLE NOT TO FACTORY SPECIFICATIONS RESIZE BORE	X X
430	REGIZE BORE	
431	MALFUNCTIONS MODELS	₹ * * * * * 2 36*****
~~******	ACCURACY	* (5 % \$ 1) # # M
	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	×
	BUTT PLATE / RECOIL PAD IS BROKEN	X
	CHAMBER ROUGH / RINGS / TEARS / TIGHT	х
	CONSIGNED GUN	X.eeeli
437	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	X
438	CREDIT RETURN	X
439	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	X
440	DAMAGES CASES, BULLETS OR SHELLS	X X
	FAILS TO FIRE	×.
442	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	×
	HEADSPACE IS EXCESSIVE	X
	MUZZLE DAMAGE	X
	NO CORRESPONDENCE	ilian X
*************	NO FAULT FOUND AT BENCH	X
	PACKING ERROR	X X
	POOR FINISH - BARREL	X
	POOR FINISH - FORE END	×
	POOR FINISH - RECEIVER (OR FRAME)	X
	POOR FINISH - STOCK	X
***************************************	RECEIVER IS MISCUT	X
	RUSTED COMPONENT SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	X
*******	SIGHTS OFF CENTER	×
	STOCK CRACKED	X
	STOCK MARRED	X
	TRIGGER PULL IS OUT OF FACTORY SPECS.	X
	CHAMBER DIRTY / RUSTY	X
	FAILS TO EXTRACT	x
	HEADSPACE AT MINIMUM	x
	LIGHT OR NO INDENT FROM FIRING PIN	×
	BLUING SALTS ARE BLEEDING FROM METAL	Х
464	EXTRACTOR MISSING	Х
465	FAULTY MAGAZINE	X
466	TRIGGER CONNECTOR BINDS	X
	EXTRACTOR IS BROKEN	X
468	FAILS TO EJECT	X
	WILL NOT FEED PROPERLY	X
	RIFLING ROUGH / MISCUT / DAMAGED	×
	ACTION IS DIFFICULT TO OPEN	×
	EXTRACTOR IS CATCHING ON SHELL HEAD	×
	MAGAZINE DIFFICULT TO LOAD	X
	POOR RECOIL PAD TO STOCK FIT	X
	ROLL MARKING VISIBLE INSIDE BORE	X
	BOLT HANDLE FELL OFF, BOLT IS BROKEN	X
	GRIP CAP IS DAMAGED	X
	RECEIVER PLUG SCREWS BROKEN RECEIVER SCOPE MOUNT HOLES OFF CENTER	X X
	BOLT FACE / SHROUD BAMAGED	X
	BORE IS HEAT CHECKED	X
	EJECTOR DOES NOT HAVE ENOUGH TENSION	X
	EJECTOR BOSS NOT HAVE BROOGH TENSION EJECTOR STUCK IN BOLT	X
	FREEBORE MISCUT / MIN	X
	SCOPE MOUNT THREADS UPSET IN RECEIVER	X
	CAMO FINISH WORN/DAMAGED	x
1.00		
487	CLOSES HARD OVER SHELL	X