I have a pre 1982 Rem 700 bolt 30-06. And would like to see if more has a pos...

Discussion Thread

3/7/2002 2:45:13 PM Response (Laura) Dear Mr. Alan, Thank you for your inquiry. We have a Safety Modification Program on certain model bolt action rifles. This is a voluntary program, it is not a recall. This is designed to remind people of the existence of the bolt-lock feature and to offer customers the opportunity to modernize their products.

You can read more information regarding our firearms and our Safety Modification program through the front page of our website or the link

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

The safe use and performance of your firearm depends on correct assembly and routine maintenance, as well as adherence to the "10 Commandments of Firearm Safety." http://www.remington.com/support/10comm.htm It is critical that you familiarize yourself with the information in both the owners manual and safety booklet. Whether you are a veteran shooter with a collection of Remington firearms, or a first time shooter, take the time to review this important literature and be certain that you are practicing firearm safety! firearm safety!

If you have any questions, please feel free to contact us at 1-800-243-9700 or 1-877-387-6691.

For nearly 40 years, the Reministran Woodel 700 Bolt-action rifle has been one of America's premier hunting rifles

Over 4 million model 700 of these rifles have been sold to hunters, target shooters and law enforcement agencies across the United States. When used following the rules of safe gun handling, including proper maintenance, and not inappropriately altered, the Remington model 700 is a safe rifle. we suggest you go to "the safety center" on our website www.remington.com

Customer (paul Alan)

I have a pre 1982 Rem 700 bolt 30-06; And would like to see if mine has a possible faulty safety as stated on CBS new 3/6/2002. Will the serial number determine if faulty?

