

I see in OUTDOORLIFE that you have a safety message about "bolt locks". I als...

Discussion Thread

Response (Laura)

4/23/2002 11:38:07 AM

Dear Mr. Sell,

Thank you for your inquiry. The Model 788 is not included in the safety modification program. You can read the complete information regarding this model and the program through the link below:

http://www.remington.com/Safety_Modification_Program/788.htm

Customer (Nathan Sell)

4/20/2002 12:49:10 PM

I see in OUTDOORLIFE that you have a safety message about "bolt locks". I also noticed that it did not include model 788. This model also needs to be in the "fire" safety mode in order to unload. Should this also be included in the safety modification program? If so, what will it take to modify it? Thanks for you reply.