

Recall? I was just informed that maybe the trigger assembly on my mohawk 600 ...

Discussion Thread

Response (Chris)

3/28/2003 10:42:51 AM

Dear Troy,

Thank you for contacting Remington Country. Your Model 600 was produced in 1976 and is not included in the recall.

If you have not had the firearm cleaned or inspected recently, we recommend taking it to one of our Remington Authorized Repair Centers for a thorough cleaning and safety inspection.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Troy Kanderka)

3/27/2003 8:06:15 PM

Recall? I was just informed that maybe the trigger assembly on my mohawk

600 308 win

is recalled? what do I do?

Thnks

Troy (Canada)