

Mod. 721

Discussion Thread

Response (Chris)

10/21/2003 10:09:35 AM

Dear Mr. Amundson,

Thank you for contacting Remington Country. According to the serial number, your firearm was produced around 1952. This firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/safety_Modification_Program/remington_safety.htm)

Customer (William Amundson)

10/17/2003 8:28:23 PM

I had a mod. 600 mohawk that had a recalled trigger at one time and was wondering if there were ever any recalls on some of the older mod. 721's. It belongs to a co-worker of mine and it seems to be "loose" and very light in pull weight. Thought I'd ask ya'll before getting another trigger for it. Ser. # 202422. I think it's pretty old. Thanks, Brett Amundson. Clifton, Tx.