Anyone who currently owns or possesses a Model 710 Rifle subject to this recall, or who purchased one and gave it or sold it to another party, should contact Remington immediately by ceiling 1-800-243-9700, or 1-336-548-8700, Monday through Friday 9 AM - 5PM EST. Remington will assist you is making arrangement to have your rifle inspected and/or repaired by a Remington Authorized Repair Center at no charge to you. To expedite repair program, Remington will send shipping tags to each customer and will cover all related shipping and repair charges. Please do not return your rifle to a Remington Authorized Repair Facility before contacting Remington on the toll-free hotline.

Remington apologizes for this inconvenience, but wants its customers to enjoy the shooting sports safely. It is important, therefore, that owners of Model 710 rifles subject to this recall participate in this program and do not use their rifles before they have been inspected and or repaired.

Safety and safe firearms handling is everyone's responsibility.

Privacy Policy <a href="http://www.remington.com/aboutus/privacy.infm">http://www.remington.com/aboutus/privacy.infm</a> | Terms of Use <a href="http://www.remington.com/aboutus/terms.htm">http://www.remington.com/aboutus/terms.htm</a> (c)2005 Remington.arms Company info All Rights Reserved.

www.remington.com <a href="http://www.remington.com"> www.remington.com</a> www.remingtonmilitary.com <a href="http://www.remingtonle.com"> www.remingtonmilitary.com</a> <a href="http://www.remingtonle.com"> www.remingtonle.com</a> <a href="http://www.remingtonle.com"> http://www.remingtonle.com</a> <a href="http:/

