

REPAIR	GUNSHOP	TOTAL	DAYS SH	INVOICE #
CLEANED AND TEST FIRED.	21147	\$10.00	1	133516
REPLACED EXTRACTOR AND PLUNGER.	21056	\$23.74	6	141655
ADJUSTED EJECTOR.	21056	\$22.00	6	141658
REPLACED MAG LATCH.	21056	\$22.00	13	138569
ADJUSTED EJECTOR.	21056	\$22.00	8	141643
REPLACED CLIP ASSY, REINSTALLED EXTRACTOR.	21056	\$30.78	44	141694
SENT TO FACTORY.	21056	\$8.50	1	138571
ADJUSTED EJECTOR.	21056	\$22.00	2	141684
ADJUSTED EJECTOR.	21056	\$22.00	2	141681
HONED CHAMBER.	21056	\$22.00	2	141670
REPLACED EJECTOR.	21056	\$25.00	1	141685
HONED CHAMBER.	21056	\$22.50	6	141630
HONED CHAMBER.	21056	\$22.00	2	141676
ADJUSTED EJECTOR.	21056	\$22.50	2	138551
REPLACED EJECTOR AND TEST FIRED.	21026	\$33.65	6	121044
SENT TO FACTORY.	21056	\$8.50	7	138673
SENT TO FACTORY.	21056	\$8.50	1	138698
HONED CHAMBER.	21056	\$22.50	6	138713
POLISHED CHAMBER.	21056	\$22.50	5	138718
HONED CHAMBER.	21056	\$22.50	6	138640
HONED CHAMBER.	21056	\$22.50	1	138711
ADJUSTED EJECTOR.	21056	\$22.50	7	138707
HONED CHAMBER, CHECKED SAFETY.	21056	\$22.50	6	138704
HONED CHAMBER.	21056	\$22.50	13	138686
ADJUSTED EJECTOR.	21056	\$22.50	7	138631
POLISHED CHAMBER, REPLACED MAGAZINE CLIP.	21056	\$31.28	1	138626
HONED CHAMBER.	21056	\$22.50	4	138637
ADJUSTED EJECTOR.	21056	\$22.50	4	138738
HONED CHAMBER.	21056	\$22.50	4	138639
HONED CHAMBER.	21056	\$22.50	7	138677
HONED CHAMBER.	21056	\$22.50	1	138676
REPLACED MAGAZINE CLIP, HONED CHAMBER.	21056	\$22.50	6	138714

Subject to Protective Order - Williams v. Remington