

KY	710	71014345	05-01	BOLT BODY WILL NOT HOLD FIRING PIN ASSY IN PLACE WHEN FIRED.	REPLACED BOLT BODY.	21072	\$14.00	11 124062
KY	710	71017860	05-01	BROKEN MAG LATCH & MAG.	REPLACED MAG LATCH & MAG.	21072	\$14.00	1 124042
KY	710	71015718	05-01	TRIGGER GUARD BROKEN, REPLACE STOCK.	REPLACED STOCK, TRIGGER ASSY & MAGAZINE.	21072	\$14.00	4 124001
KY	710	71015729	05-01	M5	TEST FIRED, FUNCTIONS OK.	21072	\$16.25	1 124075
KY	710	71015379	05-01	M5, M10	POLISHED CHAMBER.	21072	\$14.00	33 150588
KY	710	71017423	05-01	COULD NOT GET BOLT BACK IN.	CHECKED AND SLID BOLT BACK IN GUN.	21072	\$14.00	1 150581
CAN	710	71015767	05-01	BOLT HANDLE BROKEN FROM BOLT BODY.	SILVER SOLDERED BOLT HANDLE TO BOLT BODY.	21149	\$62.25	16 105221
KY	710	71022044	06-01	TRIGGER GUARD.	STOCK.	21072	\$14.00	2 150674
KY	710	71019094	06-01	M8	ROUGH BOLT.	21072	\$14.00	4 150632
KY	710	71019734	06-01	MAG LATCH.	UPDATED.	21072	\$14.00	4 150636
OK	710	71018752	06-01	TRIGGER GUARD BROKEN.	SENT TO PADUCAH FOR REPAIRS.	21047	\$20.07	4 143711
AL	710	71018568	06-01	RETURN TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 141654
SD	710	71018842	06-01	SENT TO PADUCAH.	SENT TO PADUCAH.	20510	\$12.51	1 137549
CA	710	71018582	06-01	MAG LATCH MISSING.	SENT TO FACTORY.	20801	\$18.50	1 31483
CA	710	71019821	06-01	BOLT CAME APART.	REFIT FIRING PIN ASSY & CHECKED HEAD SPACE.	20106	\$30.00	1 149360
OH	710	71020753	06-01	BAD BOLT.	SENT TO PADUCAH SHOOTERS SUPPLY.	21080	\$23.75	0 SH4522
KY	710	71021806	06-01	BROKEN TRIGGER GUARD.	REPLACED TRIGGER GUARD.	21072	\$14.00	6 124024
KY	710	71018570	06-01	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$18.00	4 150556
KY	710	71021007	06-01	FAILS TO FIRE.	REPLACED FIRING PIN ASSY AND TEST FIRED.	21072	\$16.25	4 150554

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010190

MAE00010106