

KY	710	71037393	11-01	WILL NOT FIRE.	TEST FIRED, ALL OK.	21072	\$14.00	1 124078
KY	710	71036976	11-01	BROKEN BOLT HANDLE.		21072	\$14.00	6 157565
KY	710	71036396	11-01	ISS NOT WORKING.	REPLACED FIRING PIN ASSY.	21072	\$14.00	5 157566
MS	710	71038823	11-01	WAREHOUSE INSPECTION.	WAREHOUSE INSPECTION.	107773	\$15.00	1 DK1496
AL	710	71038057	11-01	SENT BY WALMART.	RETURNED TO FACTORY.	21056	\$8.50	8 136819
KY	710	71041688	12-01	TRIGGER & GUARD BROKEN.	REPLACED STOCK & REC INSERT ASSY.	21072	\$14.00	7 124020
OH	710	71040743	12-01	BOLT STICKS.	RETURNED TO FACTORY FOR REPAIR.	21060	\$44.50	11 SH4864
KY	710	71042741	12-01	DEFECTIVE SCOPE.	REPLACED SCOPE.	21072	\$14.00	1 157591
KY	710	71042751	12-01	M5		21072	\$14.00	1 157590
KY	710	71040743	12-01	BOLT STICKS. PLASTIC SHROUD ON FIRING PIN BROKEN.	CHECKED OUT, OK. REPLACED PLASTIC SHROUD ON FIRING PIN.	21072	\$14.00	1 124074
KY	710					21072	\$14.00	5 124012
KY	710	710		CROSSHAIRS TITLED WRONG.		21072	\$14.00	5 150035
KY	710	70001519	-	UPDATE.	UPDATED.	21072	\$14.00	3 150621
KY	710	999999	-	M5	UPDATED.	21072	\$14.00	1 150662
KY	710	710025333	-	M5	UPDATED.	21072	\$14.00	5 150679
KY	710	999999	-	M5	UPDATED.	21072	\$14.00	4 150633
AL	710	999999	-	RETURN TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	5 141652
NZ	710	7107376	-	M8, M10	REMOVED RUST, BURNISHED CHAMBER, CLEANED OUT	21066	\$33.60	13 137274
CA	710	710025307	-	BOLT ROUGH.	SENT TO FACTORY.	20106	\$28.52	1 149353

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010205

MAE00010121