

REPLACED SCOPE RING.	21072	\$18.38	1	142066
UPDATED BOLT STOP.	21072	\$19.02	1	135685
INSTALLED BACKERS.	21072	\$20.00	1	139982
INSTALLED BACKERS.	21072	\$20.00	1	139990
INSTALLED BACKERS.	21072	\$20.00	1	139980
TESTED BOLT, ALL OK.	21072	\$22.00	1	139936
TESTED BOLT, ALL OK.	21072	\$22.00	1	139937
TESTED BOLT, ALL OK.	21072	\$22.00	1	139946
TESTED BOLT STOP, CHECKED BOLT HEAD ALL OK, INSTALLED BACKERS.	21072	\$20.00	2	139991
LUBED BOLT & BOLT HEAD WORKED, TESTED AND UPDATE CHECKED.	21072	\$19.47	1	142244
UPDATE ALREADY DONE, REPLACED FIRING PIN ASSY & BOLT HANDLE.	21072	\$19.47	7	135914
REPLACED BOLT BODY & FIRING PIN ASSY, INSTALLED ACTION SHIMS.	21072	\$22.00	5	139957
REPLACED BOLT BODY.	21072	\$24.02	6	136415
REPLACED BOLT BODY & FIRING PIN ASSY, INSTALLED BACKERS.	21072	\$20.00	1	139978