

Rear spacer of SPL  
MIM LH Side Plate  
removed and  
replaced with  
separate spacer  
block in Trigger  
Housing

