

Thank you for your interest in Remington products. The Buckhammer shell is scheduled for production in 2nd quarter of 2003. We hope they will begin to reach dealers late this summer. Thank you for your patience.

Used 700, not recalled

Thank you for contacting Remington Country. Your Model 700 was produced in 1996. Your firearm has not been involved in a recall. Anytime a firearm is purchased second-hand, we recommend taking it to a reputable gunsmith for cleaning and inspection to make sure it has not been altered to an unsafe condition. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state.

<http://www.remington.com/repairsvc/ModelSelection.asp>

Remington recommends that the firearm be checked periodically by the Remington Arms Co or a Remington Authorized Repair Center. This will ensure proper inspection and any necessary replacement of worn or damaged parts.

Thank you for contacting Remington Country. Your Model 700 was produced in 1973. Your firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Model 660

Dear Mr. Humble,

Thank you for contacting Remington Country. Your Model 660 was produced in 1971 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state.

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm