

Magnum = Remington makes 2 in magnum. In Magnums the stock has to be re-enforced
NON - Magnum = Remington makes only 1.

700P and 700 Varmint are the same gun just with different stocks

Centerfire = Model 700 Bolt Action and Model Seven

Model 700 Varmint

700 V - Inside dimensions bigger due to the heavy barrels - have a beaver tail forend

Free Floating = No part of BBL is touching stock
WOOD STOCKS since 1962 pressure point approx. 1.5" from fore end tip (near the front swivel stud). This helps the bbl settle back after each shot. = Better consistency with each shot therefore improving accuracy

Synthetic Stocks - Sendero/Varmint

BBL are free floated on heavy bbl models = Alum. Bedding Block in stock.

HS Precision makes the stocks for police, varmint and sendero models.

McMillian makes Custom Shop stocks only

In 2001 some stocks were bent when came from manufacturing = send these to a RARC.

Model 700 Action / Receivers

3 Ring of Steel gives the Model 700 its strength and durability
Bolt Face, Barrel and Receiver are the 3 rings of steel
Receivers are cut from one piece of steel.

Every single bbl action is tested for accuracy at the factory

Model 700 Bolt

700 Bolt issues goes to factory

Bolt is head spaced for each serial number. The last 4 digits of the serial number of the gun should match the four numbers stamped on the bolt. No bolt will work on every firearm.

If bolt handle breaks off - send the whole gun back to the factory for repair.

When bolt locked don't engage the ISS. Bolt should be open to engage the ISS

If want the new ISS on gun, must be sent to factory for update.