

Model 7400

Inertia energy – this model has to have shoulder to operate firearm properly. Very important to lean into the gun and take brunt of recoil. 7400 parts will interchange with the Model Four, butt stock will interchange with Model 742

Very important to keep chamber clean – clean with chamber brush. Clean (7400 & 7600) from bore of bbl in.