

Employee Technical Test 1187

7. What part/s are needed to replace the ejector on the 11-87?
8. When reinserting the bolt, and action bar assembly back into the receiver which latch/s is/are depressed?
 - A. First depress left latch and then right.
 - B. Lift the back of the action bar into the receiver and depress the right latch.
 - C. Stick the bolt about 1 inch into the receiver then slide the action bar sleeve over the magazine tube and slide it down under the bolt. Now depress the left latch and push the action bar assembly and bolt into the receiver.
 - D. The action bar assembly should never be removed by the consumer
9. Explain the how to field strip the 11-87 as outlined in the owners manual.
10. Explain what a "Pressure-compensated" barrel is.