FAULT CATEGORY	OLD CODE	NEW CODE	MALFUNCTIONS		MODELS
BROKEN PART	M011	M146	FORE END CRACKED	***************************************	00.0000000 00.000000 00.000000
BROKEN PART		M150	GRIP CAP IS DAMAGED		
BROKEN PART		M151	ACTION BAR IS BROKEN		1000°
BROKEN PART	M029	M152	EJECTOR BROKEN		**
BROKEN PART		M158	CHOKE TUBE CRACKED	**************************************	S*
BROKEN PART		M167	RIB LANDS ARE LOOSE	70000000	
BROKEN PART	M016	M184	MAGAZINE TUBE SEPARATED	EDOM DECEIVED	
BROKEN PART	M002	M186	ACTION SPRING TUBE FELLING		
BROKEN PART	M003	M187	BARREL GUIDE STUD MISSIN	6664. 10666000	
BROKEN PART	M004	M188	BARREL SUPPORT SERARATE		=
	101004			DENERGIBLE	=
BROKEN PART	84040	M189	CARRIER LATCH IS BROKEN	DOM DADDEL	
BROKEN PART	M013	M190	GAS CYLINDER SEPÄRÄTED I	ROW BARREL	
BROKEN PART	M054	M210	GAS CYL CRACKED	Allowania I a	
BROKEN PART	M026	M214	INTERCEPTOR LATCH STUDI	HSSING	
			**************************************	***************************************	
FAULT CATEGORY			*************		MODELS
OUT OF SPECS	M001	M101	ACCURACY		
OUT OF SPECS	M027	M104	CHAMBER ROUGH / RINGS / T	00000	
OUT OF SPECS	M064	M109	DAMAGES CASES, BULLETS (RSHELLS	
OUT OF SPECS		M112	HEADSPACE IS EXCESSIVE		
OUT OF SPECS	M017	M113	MUZZLE DAMAGE		
OUT OF SPECS	M032	M121	RECEIVER IS MISCUT		
OUT OF SPECS	M020	M124	SIGHTS OFF CENTER		
OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FA	CTORY SPECS.	
OUT OF SPECS	M058	M128	CHAMBER DIRTY / RUSTY		
OUT OF SPECS		M130	HEADSPACE AT MINIMUM		
OUT OF SPECS		M132	BLUING SALTS ARE BLEEDING	FROM METAL	
OUT OF SPECS		M144	ROLL MARKING VISIBLE INSID		
OUT OF SPECS		M147	FORE END FIT IS TOO TIGHT		
OUT OF SPECS			FORE END IS TOO LOOSE		
OUT OF SPECS	M007	200	CHOKE TUBE CONCENTRICIT	√	
OUT OF SPECS	191001	M159	CHOKE TUBE THREADS ARE		
OUT OF SPECS		M162	FIRING PIN HITS PRIMER OFF		
OUT OF SPECS		M164	RECEIVER - EJECTOR IS LOO		
OUT OF SPECS		M165	RIB DOESN'T ALIGN WITH RE		
OUT OF SPECS		1000 CO	. 1000000	ZEIVER	
		M166	RIB IS DAMAGED		
OUT OF SPECS			RIB SWEEPS TO THE LEFT		
OUT OF SPECS		M169	RIB SWEEPS TO THE RIGHT		
OUT OF SPECS		M197	CHOKE TUBE CONCENTRICIT		:L
OUT OF SPECS		M198	CHOKE TUBE CONCENTRICIT		
OUT OF SPECS		M203	EJECTOR SEAR OUT OF ADJU	SIMENT	
OUT OF SPECS	Ĭ	M204	EJECTOR SEAR TOO LONG		
OUT OF SPECS	50000000000000000000000000000000000000	M209	FRAME FACE IS ROUGH/FIRIN	G PIN HOLES RECE	ESSED
OUT OF SPECS	M047	M217	OVER LOCKED		
OUT OF SPECS		M218	PREPLAY ON SEAR NOT TO F		
MISCELLANEOUS		M102	BALANCE OF FIREARM IS NEE	DED TO PERFORM	PROPER REPAIR
MISCELLANEOUS	M053	M105	CONSIGNED GUN		<u> </u>
MISCELLANEOUS	.00000000000000000000000000000000000000	M106	COULD NOT DUPLICATE CUST	OMERS COMPLAIN	JT
MISCELLANEOUS	M062	M107	CREDIT RETURN		
MISCELLANEOUS		M108	DAMAGE APPEARS TO HAVE	OCCURRED IN TRAI	NSIT
MISCELLANEOUS	M050	M114	NO CORRESPONDENCE		
MISCELLANEOUS	M038	M115	NO FAULT FOUND AT BENCH		
MISCELLANEOUS	M045	M116	PACKING ERROR		
MISCELLANEOUS	M037	M123	SAFETY CONCERN, EXAMINE	BY PRODUCT SEE	RVICE
MISCELLANEOUS		M140	ACTION IS DIFFICULT TO OPE		·-·-
MISCELLANEOUS	1000. 1000.	M195	ACTION CLOSES TOO EASILY		
MISCELLANEOUS		M200	DEBRIS UNDER REAR CONNE		
MISCELLANEOUS	***************************************	M211			
.cccreccerrece	As.		GUN RECEIVED IN MANUAL S.		
MISCELLANEOUS		M212	GUN RECEIVED WITH SAFETY	LOCKED OFF	
FUNCTION	M044	M110	FAILS TO FIRE		