

occurred. Accuracy also seemed to be more than acceptable. The issues noted above are not show stopper ones. Not that they shouldn't be addressed or improved on if possible. Most of the planned DAT activity should be complete by the end of next week except Extended Endurance. We were not able to test a full compliment of guns for this DAT since "B-Series" guns were not tested. Due to the reduced sample size , 15 versus the usual 30, we ought to discuss a path forward to resolve those issues noted. This may involve a second DAT. Another option could be to accept the risk and head directly to T&P.

Scott Franz
Manager of Research and Technology
Remington Arms Company, Inc.
Research & Development Technology Center
Telephone: (270) 769-7607 - (0) for Operator
FAX: (270) 737-9576

MY E-MAIL HAS CHANGED to
scott.franz@remington.com

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0002263

ETE00001132