Barber8.22.060005492

Ph: 315-895-3254 Cell: 315-717-2571

From: Perniciaro, Stephen Sent: Thu 1/12/2006 7:02 AM To: Orf, Robert J. Subject: FW: Fire on Safe

FYI

From: Kelly, John W.

Sent: Thursday, January 12, 2006 6:03 AM

To: Allen, Gerald R.

Co: Pugliese, Joseph M.; Perniciaro, Stephen

Subject: FW: Fire on Safe

Jerry,

Please schedule a meeting later this morning with the folks involved in the fire control issues. We need a status update.

Thanks.

John

From: Call, Virgina L. Sent: Wed 1/11/2006 11:07 RM

To: Allen, Gerald R.

Cc: Kelly, John W.; Pugliese, Joseph M., Murray, Joseph M.

Subject: Fire on Safe

Contacted Bob Leskovar at 9:20 p.m. 1/11/06 to come in on an M/700 .338 RAMAC 27183 that had fired on safe. Bob came in & checked the gun he dry fired the gun 5 or 6 times with the safe on to check the condition before reindving it from the shooting jack. Bob took the gun to the lab for the engineers to check tomorrow: He instructed me to remove all the .338's from the gallery & checked them before shooting them. These guns were taken to Jeff Holden to checked by removing the bolt, pulling the trigger & pushing down on the sear safety cam if the sear cam went down we were tag it & hold for engineers. If the guns passed the test we were to send them back to the gallery for test. This was the 1st. of 24 guns that the test operator was to shoot he did his dry cycle & that is how he discovered that it would fire on safe. The guns were checked & sent back to the gallery all of them passed the test.

