

GUN

PROOF TEST

A-1 HAD TO HAMMER BOLT BACK. (LOT # N220C6523)
 A-2 HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
 STUCK IN BOLT AND EJECTOR STUCK BACK. (LOT # N220C6523)
 A-3 HAD TO HAMMER BOLT BACK. (LOT # N220C6523)
 A-4 HAD TO HAMMER BOLT BACK, SIGNS OF LEAKAGE, CASE
 STUCK IN BOLT, EJECTOR STUCK BACK AND BOLT HANDLE
 BROKE OFF. (LOT # N220C6523)
 A-5 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-6 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-7 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-8 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-9 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-10 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-11 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-12 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-13 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 A-14 OK

GUN

PROOF TEST

B-1 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-2 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-3 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-4 HAD TO HAMMER BOLT BACK, BROKE BOLT HANDLE OFF.
 (LOT # D15UB0623)
 B-5 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-6 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-7 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-8 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-9 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-10 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-11 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-12 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-13 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)
 B-14 HAD TO HAMMER BOLT BACK. (LOT # D15UB0623)

REDO PROOF TEST

A-2 TOOK BOLT FROM B-1 AND PUT IN A-2 HAD TO HAMMER BOLT
 BACK. (LOT # D15UB0623)
 A-4 TOOK BOLT FROM B-2 AND PUT IN A-4 HAD TO HAMMER BOLT
 BACK. (LOT # D15UB0623)