## 2<sup>ND</sup> SHIFT OPERATION REPORT REMINGTON ARMS, INC. DATE: 1/09/05

<u>SAFETY;</u> NTR

PERSONNEL;

DEPT. 8761;

DEPT. 8768;

DEPT. 8773;

DEPT. 9131;

DEPT. 9132;

**OPERATIONS;** 

8761;

<u>RIM FIRE;</u> NO ACTIVITY; WE NEED F91540M BARRELS AND F99961 RECEIVERS TO GET STARTED.

NEW GENS;

DAVE BASS FINISHED BUILDING THE 4671'S AND CONTINUED WITH THE 7063'S VINNY PESCATORE SPENT ALL NIGHTON REPAIRS.

<u>TPA'S;</u> NTR

700 FIRE CONTROL;

BLUE AND PINK PART TAGS ARE IN FSE AFTER RUNNING SEVERAL TESTS AND ASSEMBLING GUNS WITH FIRE CONTROL UNITS FROM BOTH COMPARATORS IN THE 700 BUILD AREA WE FOUND THAT THE BLUE COMPARATOR (NORTH) TESTING IN AT 4 LBS. HAD AN ACCEPTABLE TRIGGER PULL AT BUILD. THE PINK COMPARATOR (SOUTH) TESTED IN AT 4.5 LBS. RESULTING IN AN UNACCEPTABLE TRIGGER PULL AT BUILD. WE RESET THE PINK COMPARATOR TO TRIP AT 4 LBS.

NOTE: THE NEW **FIXTURES BEING** USED ON THE COMPARATORS ARE CUMBERSOME AND AWKWARD AT BEST PRODUCTION WILL SUFFER TREMENDOUSLY IF THESE BECOME STANDARD.

700 BUILD + STK ACTIONS	RIMFIRES	NEW GEN	WAREHOUSE 11:30P.M.
	0	52	

Subject to Protective Order Williams v. Remington