CODE	MALFUNCTION INDEX	700 SPS	700 SPS SS	700 BDL & ADL	700 SS	700 CDL	700 POLICE	MODEL 7
RSTL	Rear sight lössé							
MGPT-G	Missing pads at target	Store						
UNCN-G	Uncoded monconformity at target							
			iller.					
AI-P	Assembly incompleye at proof			da.				
BBB	Barrel bracket cracked or broken at proof							
BC-P	Blows cases at proof			7	S			
BEB-P	Barrel extension broken at proof							
BLP-P	Blanked primer at proof					Mar.		
BLSO-P	Barrel lug shot off at proof				*			
BP-P	Blown primer at proof		1000000					
BS-P	Barrel split at proof							
DBF-P	Damaged Bolt Face			7770				(Marie 1981)
DLOS-P	Doesn't lock over shells at proof				- "" - ###		100	100
ESB-P	Ejector sticks back at proof							
FCB-P	Fore-end cracked at proof					******		
FESO-P	Fore-end shot off at proof							
FF-P	Fails to fire at proof							
GCSO-P	Gas cylinder shot off at proof							* 400
MSI-P	Magnaflux stamp illegible on bbl							***
MSM-P	Magnaflux stamp missing on bbl							
PP-P	Pierced primer at proof							
SCB-P	Stock cracked or broken at proof							
UNCM-P	Uncoded proof malfunctions							

Barber8.22.060009524