

REMINGTON MODEL 710 EXTRACTOR ATTACHMENT METHOD TEST

TLW1811

SERIAL # 71234409

Project # 241230

DATE - 7-28-05

SHOOTER - JEFF WADE / B LEE

AMMO - REM R300W2		
MALFUNCTIONS		MALFUNCTIONS
1	51	
2	52	
3	53	
4	54	
5	55	
6	56	
7	57	
8	58	
9	59	
10	60	
11	61	
12	62	
13	63	
14	64	
15	65	
16	66	
17	67	
18	68	
19	69	
20	70	
21	71	
22	72	
23	73	
24	74	
25	75	
26	76	
27	77	
28	78	
29	79	
30	80	
31	81	
32	82	
33	83	
34	84	
35	85	
36	86	
37	87	
38	88	
39	89	
40	90	
41	91	
42	92	
43	93	
44	94	
45	95	
46	96	
47	97	
48	98	
49	99	
50	100	

DONE

83

TOTAL MALFUNCTIONS -

ROUNDS AFTER 100

ET20817

REMINGTON MODEL 710 EXTRACTOR ATTACHMENT METHOD TEST

TLW: # 1811

SERIAL # 4409

PROJECT: # 241230

DATE- 7/29/05

SHOOTER- PICA / BL

200

AMMO TYPE REM R300W2			
	MALFUNCTIONS		MALFUNCTIONS
1		51	
2		52	
3		53	
4		54	
5		55	
6		56	
7		57	
8		58	
9		59	
10		60	
11		61	
12		62	
13		63	
14		64	
15		65	
16		66	
17		67	
18		68	
19		69	
20	✓ Burished Chamber	70	
21		71	
22		72	
23		73	
24		74	
25		75	
26		76	
27		77	
28		78	
29		79	
30		80	
31		81	
32		82	
33		83	
34		84	
35		85	
36		86	
37		87	
38		88	
39		89	
40	✓	90	
41		91	
42		92	
43		93	
44		94	
45		95	
46		96	
47		97	
48		98	
49		99	
50		100	

ROUNDS AFTER 200

ET20818

REMINGTON MODEL 710 EXTRACTOR ATTACHMENT METHOD TEST

TLW: # 1811

SERIAL # 71234409

PROJECT: # 241230

DATE- 8-4-05

SHOOTER- B. LEE

200

AMMO TYPE REM R300W2	
MALFUNCTIONS	MALFUNCTIONS
1	51
2	52
3	53
4	54
5	55
6	56
7	57
8	58
9	59
10	60
11	61
12	62
13	63
14	64
15	65
16	66
17	67
18	68
19	69
20	70
21	71
22	72
23	73
24	74
25	75
26	76
27	77
28	78
29	79
30	80
31	81
32	82
33	83
34	84
35	85
36	86
37	87
38	88
39	89
40	90
41	91
42	92
43	93
44	94
45	95
46	96
47	97
48	98
49	99
50	100

ROUNDS AFTER 300

ET20819

REMINGTON MODEL 710 EXTRACTOR ATTACHMENT METHOD TEST

TLW: # 1811

SERIAL # 71234409

PROJECT: # 241230

DATE- 8-4-05

SHOOTER- B. LEE

300

AMMO TYPE REM R300W2	
MALFUNCTIONS	MALFUNCTIONS
1	51
2	52
3	53
4	54
5	55
6	56
7	57
8	58
9	59
10	60
11	61
12	62
13	63
14	64
15	65
16	66
17	67
18	68
19	69
20	70
21	71
22	72
23	73
24	74
25	75
26	76
27	77
28	78
29	79
30	80
31	81
32	82
33	83
34	84
35	85
36	86
37	87
38	88
39	89
40	90
41	91
42	92
43	93
44	94
45	95
46	96
47	97
48	98
49	99
50	100

ROUNDS AFTER 400

ET20820

REMINGTON MODEL 710 EXTRACTOR ATTACHMENT METHOD TEST

TLW: # 1811

SERIAL # 7123409

PROJECT: # 241230

DATE- 8-4-05

SHOOTER- B. LEE

400

AMMO TYPE REM R300W2	
MALFUNCTIONS	MALFUNCTIONS
1	51
2	52
3	53
4	54
5	55
6	56
7	57
8	58
9	59
10	60
11	61
12	62
13	63
14	64
15	65
16	66
17	67
18	68
19	69
20	70
21	71
22	72
23	73
24	74
25	75
26	76
27	77
28	78
29	79
30	80
31	81
32	82
33	83
34	84
35	85
36	86
37	87
38	88
39	89
40	90
41	91
42	92
43	93
44	94
45	95
46	96
47	97
48	98
49	99
50	100

ROUNDS AFTER 500

ET20821