S.A.A.M.I. JAR-OFF, DROP & ROT OFF TEST ntrol No. 444 Firecontrol Type: \(\sqrt{T4N} \) b ycles/Rounds Completed: Stock Type ement at Start (1) \(\cdot{0207} \) (2) \(\cdot{0203} \) (3) \(\cdot{0205} \) ement at End (1) \(\cdot{0229} \) (2) \(\cdot{0225} \) (3) \(\cdot{0226} \)	
PFF TEST ntrol No. 444 Firecontrol Type: 574NE ycles/Rounds Completed: Stock Type ement at Start (1) .0207 (2) .6203 (3) .0205	
ntrol No. 444 Firecontrol Type: 574NE ycles/Rounds Completed: Stock Type ement at Start (1).0207 (2),6203 (3).0205	
ntrol No. 444 Firecontrol Type: 574NE ycles/Rounds Completed: Stock Type ement at Start (1).0207 (2),6203 (3).0205	
ycles/Rounds Completed: Stock Type ement at Start (1) . 0207 (2)	Date: 1-7-04
ement at Start (1) .0207 (2) .6203 (3) .0205	
ement at Fnd (1) . 0229 (2) 022 (3) 022	Average . 6205
	6 Average <u>.0226</u>
No. Serial No.	
er Pull at Start of Test (1) 3.934 (2) 4.090 (3) 4.178	(4) <u>4./36</u> (5) <u>4.05</u> ⁴
ge Trigger Pull at Start of Test: 4.078 Std. Dev. of Trigger Pull at End of Test (1) 4.265 (2) 4.301 (3) 4.288	gger Pull at Start of Test:
r Pull at End of Test (1) 7-265 (2) 4,30/ (3) 4,288	(4) 4 < 8 < (5) 4.008
ge Trigger Pull at End of Test: 4.241 Std. Dev. of Tri	Tester Initials:
Additional Notes and Comment	
Jar-off requalification	83
- 17 kg	
For additional details on the proper procedures to be used	for this Test Procedure refer to
	/in 1000 1000 1000 1000 1000 1000 1000 10
ANSI/SAAMI Z299.5-199	10
SAAMI Specifications for Standard Jar-Off Test;	Ter 17
Jar-Off Test: 12-inch drop - onto 1" thick 85 Durome	oton (Chono A) Deibban Matt
Fine on ready to fire, Safe in "Fire" po	eier (Shore A) Kubber Mall
Chamber, Magazine loaded to capacity	with Dummy Rounds
After each drop, fire Primed Case to ve	
	V
12 inch drop (safety in "Fire" position) - one d	drop per orientation.
Note: for Firearms with the ISS system installed – The I	SS will be set in the unlocked
position for all six orientations of the .	Jar-Off Test
Orientation ISS Unlocked	Comments
arrel Vertical, Muzzle Up: Pass Fail	
	•
arrel Horizontal, Bottom of Stock Down: Pass Fail	
Notes: (continue on back of sheet if necessary)	
Did 5x Barnel Herizontal, Button	n of stuck Down passed
ay 5 araps.	Tester's Initials
	Page 1 of 3

ET21430