

TRACKING #TLW1447
PROJECT #241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
SW/JS	7/23/04	Head space	Min +.002	TLW1447A	
"	"	Head space	Bolt Type GO won't close	"	
SW/JS	7/25/04	Proof Rd	OK - Hammer bolt back	TLW1447B	1
"	7/26/04	Head space	Min +.003	TLW1447C	
"	"	Head space	Bolt Type GO won't close	"	
SW	7/26/04	Firing Pin Indent	.019, .018, .018 Avg. .0183	TLW1447D	
"	7/27/04	Check Loosening Torque	Front screw 34 in lbs	TLW1447E	
"	"	Check Depth of Front Take down screw hole	.0141	"	
"	"	Check number of turns to loosen front screw	2 turns	"	
"	"	Inspect thread & measure length	OK / 1.4445	"	
"	"	Engagement	.0346, .0344, .0344 Avg. .03446	TLW1447E	
"	"	Trigger Pull		TLW1447F	
"	"		4.536, 4.569, 4.568, 4.573, 4.596 Avg 4.568	"	
SW	7/28/04	Sec. 1: ft	.0165	TLW1447E	
SW	7/29/04	Torque Front screw	70 in lbs	TLW1447	
SW	7/30/04	200 Rd Basic Back Function Test		TLW1447P	200
BL	5-6-04	Clean Bore & Bolt			
PKR	5/20/04	Burnish Chamber			
"	"	Function Test	100 Rds	TLW1447A	
SW	8/2/04	"	"	"	100
SW	8/23/04	Endurance	400 Rds	TLW1447A	400
SW	8/25/04	Clean & Inspect	Head space Min +.003	TLW1447S	701

FORMS.XLS