

TRACKING #TLW1447
PROJECT #241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	TOTAL RDS.
				RDS. FIRED	
SW/JS	4/28/04	Head space	Min +.002	TLW1447A	
"	"	Head space	Belt Type GO won't close	"	
SW/JS	4/28/04	Prop Rd	OK	TLW1447B	1
↓	4/26/04	Head space	Min +.002	TLW1447C	
↓	"	Head space	Belt Type GO won't close	"	
SW	4/26/04	Firing Pin Indent	.018, .019, .018 Avg. .0183	TLW1447D	
↓	4/27/04	Check Loosening Torque Front Screw	30 in lbs	TLW1447E	
↓		Check Depth of Front Trigger Down Screw Hole	.0142	↓	
↓		Check Number of Turns to Loosen Front Screw	1 3/4 Turns	↓	
↓		Inspect Threads & Measure Length	OK / 1.4405	↓	
↓		Engagement	.0329, .0329, .0329 Avg. .03290	TLW1447F	
↓		Trigger Pull	4.980, 4.866, 4.993, 4.838, 4.945 Avg. 4.924	"	
SW	4/28/04	Sew 1st	.0131	TLW1447E	
SW	4/29/04	Torque Front screw	30 in lbs	TLW1447	
SW	5/3/04	200 Rd Basic Jack Function Test		TLW1447D	200
BL	5-6-04	Clean Bolt & Bolt			
BL	5-13-04	Ext Function & Endurance Test	O-Mat Functions	TLW1447B	500
SW	5/19/04	Clean & Inspect Head space	Min +.002	TLW1447S	201

THIS SHEET IS TO ACCOMPANY THE FIREARM AT ALL TIMES THROUGHOUT TESTING

FORMS.XLS

ET21704

Confidential - Subject to Protective Order

Williams v. Remington