

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 122 105

Gun Test # A23

S/N 71203190

Round Level: 721

Inspector: B. LEE

83

- ☒ Measure Headspace min+.005
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 10, Center 10, Rear 10
- ☒ Sear Engagement: 1st. .0278 2nd. .10288 3rd. .10302 Ave. .0287 spec-.025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.668 2nd. 4.577 3rd. 4.592 Ave. 4.612 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☐ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21860