

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 17 105

Gun Test # A-1

S/N 71202770

Round Level: 701

Inspector: B LEE

83

- ☒ Measure Headspace min .004.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 40, Center 25, Rear 15
- ☒ Sear Engagement: 1st .0239 2nd .025 3rd .0251 Ave. .0246 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 5.097 2nd 5.173 3rd 5.033 Ave. 5.101 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22171