		IDENTIAL
		rms Company Inc. Iopment Technical Center
	315 W	est Ring Road
	Elizabeth	town, KY 42701
	Clean & I	nspect Checklist
	Model: 710 Extru	ded Receiver "Std. Caliber"
	Project: 241314	TLW #: TLW1689
	Date: 2 / 17 / 05	
	Gun Test # <u><u>A</u>3</u>	S/N 71203229
/	Round Level: <u>70/</u>	Inspector: <u>B. LEE</u> 83
Measure Headspa	ce <u>mint.007</u> .	
Check Takedown	Screw Torque @ Disassembly: Frt_	<u>35</u> , Center 25, Rear <u>10</u>
Sear Engagement:	1 <sup>st</sup> 0245 2 <sup>nd</sup>	2.97 Ave
Reset Sear Engage	ement if Required: 1 <sup>st</sup> 2 <sup>nd</sup> .	3 <sup>rd</sup> . Ave
Trigger Pull:	1 <sup>st</sup> . <u>6.147</u> 2 <sup>rd</sup> . <u>5.675</u> 3 <sup>rd</sup> . <u>5.9</u>	Ave. <u>5. 93/</u> spec- 4 lb. to 5.5 lb.
Reset Trigger Bull	if Required <sup>211st</sup> . 5.0362 <sup>nd</sup> . 4.	Ave. 5.033
Inspect Fireconti	el Insert for any signs of cracking o	r other
👘 failure. 🏠	<u>o</u> K	
		•
Left ther items of		
note:		· · · · · · · · · · · · · · · · · · ·
<u> </u>		
	······	
<del></del>	·	
		· · · · · · · · · · · · · · · · · · ·
Torque Takedown	Screws @ Reassembly: SPEC- Frt	- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.
		TLW1216
		•
	Remington (	Confidential
		Jonnaonnai

.

## ET22218

Confidential - Subject to Protective Order Williams v. Remington