

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-9

TLW #: TLW1216

Date: 8 / 20 / 03

Inspector: SW/BL

Round Level: 221

- ☒ Measure Headspace min +.007 83
- ☒ Sear Engagement: 1st. .0248 2nd. .0251 3rd. .0250 Ave. .02496 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.065 2nd. 4.076 3rd. 3.958 Ave. 4.033 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Wear on Bolt stop
- ☒ Inspect stock for any signs of cracking or other failure. Lower corner of recoil bracket has cracks on stock
Crack on middle take down screw hole.
- ☒ Other items of note: Bolt stop does not lock bolt in place, Top of magazine has
Some protrusion, wear in magazine latch area

TLW1216

Remington Confidential

ET22334