

CAL 300 WIN MAG

DAT # 1 M/710 MAGNUM PRODUCTION RECEIVER INSERT

TRACKING # TLW1216
PROJECT #241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/BL	8/28/03	Scope Endurance Test	Accuracy After 30 Rds OK TLW1216AK	30	341
SW/BL	9/03/03	Extended Function & Endurance Test	magazine Box having Problem Extracting From magazine well - 0 malfunctions - Photo Taken TLW1216R	500	841
BL	9/3/03	Cleaned	TLW1216S		
SW	9/3/03	Inspection	Head space Min +.007 TLW1216S		
BL	9/8/03	Magazine Box Change	A-5 magazine Box in A12 and A12 magazine Box in A5		
SW/BL	9/10/03	Extended Function & Endurance Test	Total malfunctions 9 FTE - 13 FTE EXTRACT Extractor is not extracting empty cartridge From chamber TLW1216R	500	1241
BL	9/10/03	Cleaned	TLW1216S		
SW/BL	9/10/03	Inspection	Head space Min +.007 TLW1216S		
BL	9/10/03	Bolt Head	Sent to Mayfield to replace extractor		
BL	9/12/03	Bolt Head	replaced extractor and returned to Etown		
BL	9/12/03	Ejector Test	OK	20	1261
BL	9/15/03	Extended Function & Endurance Test	malfunctions 20 FTE EXTRACT - 14 FTE Stopped at 1470 Rds TLW1216R	420	1731
PKR	9/22/03	Bore Obstruction Test	obstruct bore with one 220 Gr. 30 cal. bullet, load & fire remotely one Std. 300 WM 180 Gr. PSP Round. Document on Digital Video - Gun was damaged		

Logform

Confidential - Subject to Protective Order

ET22505