		- selective and			
400 Rd. Extended	Function Test	Guns C-6 to C	1		İ
TLW0300AA		336 320. 58 19			
12/20/00		174	i ———		
					
This is a 400 rd. The	tonded Eupstion To	st performed in the Function & Casualty Ra	non union the r	d Pomiagton t	post inche
			inge daing the s	d. Rennigion t	T T T T T T T T T T T T T T T T T T T
		ed in no certain order or amount	0.44511	220/15 114 0 5	7540/4
GUNS C-11 TO C1	5 HAD ADDITIONA	L CLEARANCE MACHINED INTO THE MA	G WELL TO IM	PROVE MAG F	REMOVAL
		2,000			<u> </u>
Gun #	Serial #	Ammo Types	lot#	Rds. Fired	Malfunctions
C-6	71001683	Rem. R30064, 180 gr.SP	K29G C4214	100	0
	l	Rem. L30062, 150 GR. MG	M03G B1	100	0
		Fed. P3006Q, 165 gr.	01.9614X250	100	0
		Rem. R30064, 180 gr.SP	K29G,C4214	100	0
Technician-	Jesse Arnold	16.7	*32V:		
Comments Noted-	Magazine box beco	ome very difficult to remove form gun, straig	htened mag bo	x 220 rds. into 1	test & continue.
		3	- c 1000 500		
GUN#	Serial #	Ammo Types	Lot#	Rds. Fired	Malfunctions
C-7		Rem. R30064, 180 gr.5P	K29G C4214	100	0
U-7	71001034		M03G B1	100	0
	ļ . 		410331X227	100	0
	 	Fed. 3006b, 180 gr.		-38	
<u> </u>	ļ	Win. S3006XB, 150 gr.	ME61	100	7 STEM LOWS
Technician-	Jesse Arnold	L	portugation acceptance		
Comments Noted-	Magazine box bec	ome very difficult to remove form gun, straig		Y:= 1 214.8	4 rds. Into test & continue.
			الماري الماري الماري	78.	
GUN#	Serial #	Ammo Types	Lot #	-Rds. Fired	Malfunctions
C-8	71002501	Rem. R30064, 180 gr.SP	K296 C4214	100	0
		Rem. L30062, 150 GR. MC	M03G B1	²⁻ 100	0
		Win. SBST3006XA, 168 gr.	04RK81	100	· 0
		Rem. R30065, 180 gr. PTD SP	L19D B27	్రై 100 ్లో	0
Technician-	Jesse Arnold		1,6	1	
Comments Noted-	Magazine box bec	ome very difficult to remove form gun, straig	htened mag bo	x 200 mgs. into	test & continue.
				49	(And 2)
GUN#	Serial #	Ammo Types	Lot #	Rds. Fired	Malfunctions
C-9		Rem. R30064, 180 gr.SP	K29G C4214	100	mag box bottom came off @ 93 & 100 rds
C-3	71001425	Rem. L30062, 150 GR. MC	M03G B1	100	0
ļ	 	Win. SHV30064, 180 gr.	35PC52	190	
	 			100	.s. 0
	 	Rem. L30062, 150 GR. MC	M02G C1	100	
Technician-	Jesse Arnold	<u> </u>	L	L	1 (Mary 1977)
Comments Noted-	Magazine box bec	ome very difficult to remove form gun, straig	phtened mag bo	x 200 rds. into	lest & continue.
	ļ		<u> </u>	_ · · · · · · ·	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
GUN#	Serial #	Ammo Types	Lot#	Rds. Fired	Malfunctions
C-10	71002554	Rem. R30064, 180 gr.SP	K29G C4214	100	mag box bottom came off @ 49,53,65,70,84 & 96 rds.
	i	Rem. L30062, 150 GR. MC	M03G B1	100	2 stem lows 0
		Fed. P3006G, 150 gr.	A146782320	100	0
					Q.

ET34158