

Technician-	Jesse Arnold	Rem. R30067, 220 gr.SP	M24HB14	100	mag box bottom came off @ 22 & 32 rds.
Comments Noted-	Magazine box become very difficult to remove from gun, straightened mag box 200 rds. into test & continue.				
GUN #	Serial #	Ammo Types	Lot #	Rds. Fired	Malfunctions
C-11	71002555	Rem. R30063, 150 GR. BR PT	J26N B97	160	mag box bottom came off @ 24 rds.
		Win. S3006XB, 150 gr.	ME61	50	3 STEM LOWS
		Win. SHV30064, 180 gr.	35PC52	50	0
		Fed. P3006G, 150 gr.	A146782320	70	0
		Fed. 3006b, 180 gr.	41047X228	10	0
		Fed. P3006Q, 165 gr.	010614X250	30	0
		Rem. L30062, 150 GR. MC	M03G B1	20	0
		Win. SBST3006XA, 168 gr.	04BK31	10	0
Technician-	Jesse Arnold				
Comments Noted-	None				
GUN #	Serial #	Ammo Types	Lot #	Rds. Fired	Malfunctions
C-12	71001680	Rem. R30064, 180 gr.SP	K28 GB3714	100	0
		Rem. L30062, 150 GR. MC	M03G B1	300	0
Technician-	Jesse Arnold				
Comments Noted-	None				
GUN #	Serial #	Ammo Types	Lot #	Rds. Fired	Malfunctions
C-13	71001686	Rem. PRT3006B, 165 GR. NOL. BAL TP	M31A C26	100	1 BOLT OVER-RIDE
		Rem. L30062, 150 GR. MC	M03G B1	300	0
Technician-	Jesse Arnold				
Comments Noted-	None				
GUN #	Serial #	Ammo Types	Lot #	Rds. Fired	Malfunctions
C-14	71001787	Rem. R30064, 180 gr.SP	K28 GB3714	100	mag box bottom came off @ 7 rds.
		Rem. R30065, 180 gr.PTD SP	K04U A7926	60	0
		Rem. PRT3006B, 165 GR. NOL. BAL TP	M31A C26	20	0
		Rem. L30062, 150 GR. MC	M03G B1	200	0
Technician-	Jesse Arnold				
Comments Noted-	None				
GUN #	Serial #	Ammo Types	Lot #	Rds. Fired	Malfunctions
C-15	71001948	Rem. L30062, 150 GR. MC	M03G B1	264	0
		Rem. R30064, 180 gr.SP	K28 GB3714	78	0
		Rem. R30065, 180 gr.PTD SP	K04U A7926	33	0
		Rem. R30063, 150 GR. BR PT	J26N B97	25	0
Technician-	Jesse Arnold				
Comments Noted-	None				

83

ET34159

Confidential - Subject to Protective Order
Williams v. Remington