

**Bob Orf**

---

**From:** Becker, Craig  
**Sent:** 09/23/2005 04:06:08 PM  
**To:** Orf, Robert J.  
**CC:**  
**BCC:**  
**Subject:** Activities for week ending 9/24/05

Bob,

This week, I worked on the following:

SPL issues. Steve has assigned some of Jim Doolittle's minor responsibilities to me. Additionally, Jim isn't afraid to ask for help.

I have been coordinating getting triggers, sear safety cams and trigger housing assemblies ready for the upcoming run-offs. I am also writing TDR's, And submitting purchase requisitions for the project.

There were some problems with conventional 700, 40X and SWS Fire controls this week. We have been having trouble getting 6-40 tapped holes to stay in gage. I've been working with Cutter Grind and Grippe to resolve.

I'm working on the PPI for the M750 gas lug. I've been Helping Terry Kalka and Mike LeMay on this.

I was called to resolve a minor problem with M/700 SA firing pin assemblies.

That is the highlights for this week.

Craig S. Becker  
Manufacturing Engineer  
Remington Arms Co. Inc

14 Hoefler Ave.

Ilion, NY 13357

(315) 895-3207

(315) 895-3670 (Fax)

E-mail: [craig.becker@remington.com](mailto:craig.becker@remington.com)