

My model 700 V you can't open the bolt with the saftey on. This is an
ol...

Discussion Thread

Response (Laura) 1/30/2001 1:56:10 PM

At 01/30/2001 10:54 AM we wrote -

Dear Sir/Madam,

According to the serial number provided, it appears this firearm was produced in or around 1975. Model 700 rifles manufactured before 1982, and some other older Remington rifles (Models 721, 722, 788, 600, and 660 series) were manufactured with a "bolt lock" feature. The purpose of the bolt lock, which was favored by many hunters, was to prevent accidental lifting of the bolt, for example, by heavy brush. This feature requires the manual safety to be placed in the "fire" position before the bolt can be raised and the firearm unloaded.

If you have a rifle with a bolt lock, you must take special precautions when unloading your rifle. Remember the first Commandment of Firearm Safety: ALWAYS KEEP THE MUZZLE OF YOUR RIFLE POINTED IN A SAFE DIRECTION! Always unload your rifle in the field: never carry a loaded rifle in a vehicle or to your hunting camp

You can read more about our bolt action rifles through the front page of our website at www.remington.com.

Customer (John R Rogers) 1/28/2001 2:48:32 PM

My model 700 V you can't open the bolt with the saftey on. This is an older rifle it has a machine groove cut into the bolt is it designed that way?

Can you tell me a history on this rifle?

Thank You.