

my model 600 has the two part sear in it's trigger. is this one of the model...

Discussion Thread

Response (Laura) 2/19/2001 7:40:59 PM
At 02/15/2001 10:24 AM we wrote -
Dear Mr. Brost,
Please contact our Parts and Repair Department at 1-800-243-9700. We need to speak to you in more detail regarding your inquiry.

At 02/19/2001 04:39 PM we wrote -
Dear Mr. Brost,
The trigger assembly is a restricted part. Any updates can only be performed by our factory gunsmiths. You will need to send the firearm to the following address:

Please follow these guidelines:

1. Record the serial number of your firearm before sending it to us.
2. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box.
3. Remove all accessories from your firearm to prevent loss or damage.
4. Enclose a letter with the firearm detailing the model name or number of your firearm and serial number along with a full description of the problem. Be sure to include your full name and address (P.O. Box and Street Address), including zip code, daytime telephone number, and e-mail address.
5. Ship your firearm by either United Parcel Service (UPS) or Parcel Post (US Post Office). Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Ship to:

Remington Arms Company, Inc.
Attn: Arms Services Division/Repairs
14 Hoefler Avenue
Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

Customer (TERRY BROST) 2/13/2001 4:55:15 PM
my model 600 has the two part sear in it's trigger. is this one of the models you've had problems with? if so, where can i obtain a replacement trigger? i am a qualified gunsmith so install is not a problem.
thank for your assistance
terry brost
t l brost gunsmithing
1078 road 10
lovell, wyoming 82431
307 548 6530
ffl#5-83-003-01-4A-00069

At 02/16/2001 11:44 AM you wrote - contacted the 800 number and talked to a lady who could only read from a computer screen, not offer any real

help. her best suggestion was send the entire rifle to ilion, ny for company repair. i am a qualified gunsmith and just want the parts. my rifle does not have the v stamped on the trigger housing, which the lady said signified previous update to the trigger. i do not want to send the entire rifle out. would it be possible to exchange the trigger unit only?