The bolt on my 700 BDL .25-06 does not lock down the bolt when the safty is l...

Discussion Thread

Response (Inez) 10/26/2001 9:\$5:56 AM
At 10/26/2001 09:54 AM we wrote Dear Randy,
Our older Model 700's came equipped with a bolt lock safety. These are no
longer available and cannot be retrofitted. We hope this inforamtion is
helpful and we appreciate your visit to Remington Country.

Customer (Randy De Coteau) 10/24/2001 11:52:59 PM ---- 10/24/2001 11:52 PM ----- The bolt on my 700 BDL .25-06 does not lock down the bolt when the safty is locked. Is there anything I can do to change this so the bolt will not open? I know that on some models this is so; but it may be because they are older rifles.

