

1. What year was my Remington 700 (22-250 cal.) manufactured in? 2. What is t...

Discussion Thread

Response (Nicole)  
Dear James,

4/26/2002 1:50:58 PM

Welcome to Remington Country and thank you for your inquiry. According to the serial# you provided your Model 700 was produced in about in 1973 with the rate of twist 1 in 14.

We are offering the modification on all pre-82 bolt lock firearms.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/Support/repairsvc/ModelSelection.asp>

Customer (James Keffer)

4/24/2002 7:43:15 PM

1. What year was my Remington 700 (22-250 cal.) manufactured in?

2. What is the twist rate for this rifle?

3. Does this rifle require the safety change for the bolt/safety ( I can not unload the rifle with the safety on).