

Dear sir, I just purchased the above discribed rifle. It is a 7mm Mag. in a l...

Discussion Thread

Response (Jason)

12/27/2002 9:22:18 AM

Dear Harry:

Your Remington Model 700 was made in April of 1980. This would confirm the story of the gentleman from whom you purchased the rifle. The barrel is not supposed to be free floated. The stock is designed to have a "pressure point" towards the end. We have found in testing that our firearms tend to have more reliable accuracy without free floating the barrels. However, it should not touch any other place but that.

Your firearm is also eligible for the Safety Modification program. On any pre-1982 Model 700, you can send in your firearm and we will modify it so that you can load and unload your firearm with the safety on. The cost is \$20 per firearm through the end of the year. You can find the details here:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm.

I hope this information helps. Please let us know if you need anything else.

Customer (Harry Peterson)

12/21/2002 6:55:13 PM

Dear sir,

I just purchased the above discribed rifle. It is a 7mm Mag. in a left hand model. The original owner never put the fist round through it. It is virtually brand new. He claims it was purchased in the very early 1980's. Can you confirm the production date as the history section of your inter-net page will not open on 700's. Second question-Is this rifle barrel suppose to be "free floated" or is it a glassed in barrel, as I am unable to slide a dollar bill under the barrel between it and the stock forearm. Any other information you may have on this rifle would greatly be apriciated. Thank you for your time in this matter!! Harry Peterson.