

I was recently told by a gunsmith up here in Canada that the barrel on this 1...

Discussion Thread

Response (Chris)  
Daer Bruce,

10/16/2003 12:50:45 PM

Your Model 700 was produced in 1981. Your firearm has been involved in a recall. Please contact the following Remington Repair Center that is authorized and can test a replacement .17 caliber rifle barrel. If the the repairman have any questions regarding the recall, they can call me direct at 800-243-9700, extension 8705, Mon-Fri 9-5 EST.

In addition, your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Bruce Waddell)

1/20/2003 1:14:26 AM

I am not sure of what to beleive anymore, first when I called I was told that this gun was involved in a barrel recall and to find a dealer to change the barrel for me. I have not been able to find a dealer in Canada that can do it and upon calling Remington today and talking to a Derrick I was told that this gun in not involved in a recall. Please let me know one way or the other.

Thanks again  
Bruce