

I recently purchased a Remington Model 700 Mountain Rifle LSS and noticed you...

Discussion Thread

Response (Chris)

2/5/2003 10:12:05 AM

Dear Mr. Mason,

If you are able to open the bolt with the safety still on, you do not have a bolt-lock safety, which meant you would have to put the gun on fire before you could unload.

Your Model 700 Mountain rifle was produced in 2002. It is described as an LSS Mountain with 22" stainless barrel, 30-06 caliber, with a brown laminate stock.

Customer (Phillip Mason)

2/3/2003 11:02:45 PM

I will check with a Remington Authorized Center. However, I also question whether the rifle I purchased could not have been a composite of perhaps an older action and a Mountain Rifle LLS lookalike stock and not actually be a Mountain Rifle LLS model. Can this be determined by the serial number?
Phil Mason