I have a Remington 721 in a 270 that was manufactured in 1948. I have been to...

Discussion Thread

Response (Chris) 2/4/2003 2:49:00 PM
Dear Mr. Costello,
Thank you for contacting Remington Country. We are offering to convert
your bolt-lock safety to a non-bolt-lock safety. After the conversion,
you would be able to work the bolt with the safety \$\frac{1}{2}\$till on. To view more
information on the conversion, go to:
http://www.remington.com/Safety_Modification_Program/remington_safety.htm

We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

http://www.remington.com/repairsvc/ModelSelection.asp

Customer (Frank Costello) 2/4/2003 6:16:03 AM I have a Remington 721 in a 270 that was manufactured in 1948. I have been told I can have a safety update as on some 700 models for \$20.00 Please advise if this is true and where to send the rife. Will await your reply, thanks Frank Costello.

