

safety modification program

Discussion Thread

Response (Jessica)
Dear Thomas,

9/25/2003 9:17:02 AM

If the Model 600 does not have the "V" stamped on the trigger both the modification and recall will be at no charge. The Model 721 will have an approx. charge of \$20.00 for the modification and \$10.00 for shipping. If any problems are found with the firearm they may provide you with an estimate of what needs to be done and the cost.

Customer (thomas biss)

9/19/2003 2:14:39 AM

thanks for the last reply that was what i wanted to know i hope that there is nothing else wrong with my rifle besides that everything else works like it is supposed to. Both rifles will be sent in after hunting season is over to your company from our local gun shop.

thanks,

thomas biss