

Near Tragic Misfire...

Discussion Thread

Response (Chris)  
Dear Mr. Dais,

12/23/2003 12:50:46 PM

We apologize for the delay. According to the serial number, your rifle was produced in 1974. Your firearm has not been involved in a recall. Your firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/safety_Modification_Program/remington_safety.htm)

We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

Customer (William Dais)

12/16/2003 9:40:53 AM

More than three business days have passed, and still no answer to the question.  
Please respond.