

Model 700 rifle safety

Discussion Thread

Response (Dell)

3/9/2004 4:31:27 PM

Dear Joe,

Thank you for your inquiry. We are not aware of any safety concerns with the Model 700. If you have an older Model 700, we are offering an optional update to the rifle. The following link will tell you what to do.

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Concerning the Model 51: we no longer house any parts for this model. For your convenience we have included a link below to a list of establishments that may offer parts or services for your older Remington firearm:.

<http://www.remington.com/support/parts/obsolete.htm>

Additional information regarding parts and service can be found in our Support Section under "obtaining Services".

Customer (joe terry)

3/8/2004 12:23:34 PM

I have a 30 06 700, which I love, but I have heard talk of a safety problem with accidental discharge when the safety is on while loading? Is this true? The sn is 132620.

I also have a Remington pistol model 51 that has a broken bolt carrier (cal 380). Do you know where I can get a replacement? I have tried 10 large dealers across the country.