Model 700 Classic

Discussion Thread

Response (Denis) 3/23/2004 2:14:05 PM Dear Mark, We appreciate your interest and support of Remington products. Please return the firearm to the factory so that we may check the trigger pull for you. If it is out of spec, we will adjust accordingly. Using an independent gunsmith to "adjust" your trigger will void the warranty on the trigger and can result in an unsafe firearm if not adjusted correctly or too light. As to the Model 200 holt lack matter.

As to the Model 700 bolt lock modification, this will NOT convert the safety to a 3 position safety. It simple allows the bolt to move freely for unloading purposes while the safety is an the "safe" position. Please use the link below for more details. This voluntary modification is offered for \$20.00 through our factory or authorized repair centers throughout the country.

http://www.remington.com/Safety\_Modification\_Program/remington\_safety.htm

Customer (Mark Johnson) 1/20/2004 8:19:50 AM 1 have a model 700 Classic in .338 WIN Mag.1 lave the gun, BUT! It has what 1 percieve to be an overly heavy trigger pull.Doas Remington do trigger adjustments, or do I need to go to an independent gunsmith?There is a Remington autherized service center not too far from me in Fairfield Ct.Can I take the gun there instead of shipping it?I also own a 700 ADL that qualifies for the bolt release modification and would like to know if this changes the gun to an actual 3 position safety, or if it just makes it so it will open in the existing SAFE mode.I will leave it as is if it will alow my bolt to open unexpectedly while going through brush, or removing from a scabbard, ect. what is the aproximate turnaround time on this modification? modification?

